

OT Roll Offs

2/11/2015

Number	Status		Analyzed	Approved
OT 25563	Sand Trench Residue			Current
OT 25337	Empty			
OT 25474	Empty			
OT 25480	Fine material, soil sand from North Pond Asphalt	6	No	
OT 25160	Sand from Warehouse	6	No	
OT 25452	Sand from Warehouse	6	No	
OT 25319	Debris (ADS Hose, Wood,Pails, Plastic, PPE)	7	No	
OT 25134	Debris (Pails, PPE, Wood)	7	No	

Vacuum Boxes

Donated

2/11/2015

Number	Status	Composite	Analyzed	Approved
VB 2564	Sludge from WWT Area	Sludge Comp 3	Received Results	24"
VB 25318	Sludge S T 2	Sludge Comp 5	Received Results	37 "
VB 25306	Sludge S T 2, S T 5	Sludge Comp 5	Received Results	36.5"
VB 25302	Sludge N T 3, N T 5, N T 6, S T 8	Sludge Comp 3	Received Results	36"
VB 2501	Sludge N T 3, N T 5, N T 6, S T 8	Sludge Comp 3	Received Results	36"
VB 25278	Sludge N T 9, N T 10, N T 11	Sludge Comp 5	Received Results	36.5"
VB 25226	Sludge S T 3, S T 5, S T 7	Sludge Comp 2	Received Results	36"
VB 25348	Sludge S T 5	Sludge Comp 3	Received Results	36"
VB A 0825097	Sludge ST 5	Sludge Comp 3	Received Results	36"
VB A 785	Sludge ST 5			36"
VB 25287	N OT 7			36"
VB 25206	Sludge ST 5			36"
VB 25274	Sludge ST 5			36"
VB 25315	Empty			
VB 25333	N OT 8			Active
VB 25341	Sludge ST 8			36"
VB 25251	Sludge ST 8			36"
VB 25322	Sludge ST 8			36"
VB 25146	Empty			
VB 25281	Empty			

VB 25343	Empty			

Dewatering Box

Number	Status		Analyzed	Approved
VBDW 25196	N OT 8		No	28"